



12 South Center Street
Bensenville, IL 60106

Office: 630.350.3404
Fax: 630.350.3438
www.bensenville.il.us

VILLAGE BOARD

President
Frank Soto

Board of Trustees
Rosa Carmona
Frank DeSimone
Susan Janowiak
Agnieszka "Annie" Jaworska
Martin D'Connell
Henry Wasseler

Village Clerk
Ilsa Rivera-Trujillo

Interim Village Manager
Frank Kosman

February 26, 2016

Ms. Lindsey Sorensen
560 5th Street NW, Suite 301
Grand Rapids, Michigan 49504

Re: February 24, 2016 FOIA Request

Dear Ms. Sorensen:

I am pleased to help you with your February 24, 2016 Freedom of Information Act ("FOIA"). Your request was received by the Village of Bensenville on February 24, 2016. You requested copies of the items indicated below:

"Village records pertaining to 1077 & 1081 Sesame Street."

After a search of Village files, the following documents are enclosed to fulfill your request:

- 1) Village of Bensenville Records Pertaining to 1077 & 1081 Sesame Street. (18 pgs.)

These are all of the documents that can be discovered responsive to your request.

For additional information pertaining to zoning of the property, please contact Village Planner, Victoria Benham, at 630-766-8200.

Section 7(1)(b) of FOIA provided that "private information" is exempt from disclosure. "Private information" is defined in FOIA as, "unique identifiers, including a person's social security number, driver's license number, employee identification number, biometric identifiers, personal financial information, passwords or other access codes, medical records, home or personal telephone numbers, and personal email addresses. Private information also includes home address and personal license plates, except as otherwise provided by law or when compiled without possibility of attribution to any person." 5ILCS 140/2(c-5). Consequently, certain unique identifiers have been redacted from the records being provided.

Pursuant to Section 9 of the FOIA, 5 ILCS 140/9, I am required to advise you that I, the undersigned Freedom of Information Officer, reviewed and in consultation with an attorney for the Village, made the foregoing determination to deny a portion of your FOIA Request as indicated. Should you believe that this Response constitutes an improper denial of your request, you may appeal such by filing a request for review within sixty (60) days of the date of this letter with the Public Access Counselor of the Illinois Attorney General's Office, Public Access Bureau, 500 South Second Street, Springfield, Illinois 62706; telephone 1-887-299-FOIA; e-mail: publicaccess@atg.state.il.us. You may also have a right of judicial review of the denial under Section 11 of FOIA, 5 ILCS 140/11.

Do not hesitate to contact me if you have any questions or concerns in connection with this response.

Very truly yours,


Corey Williamsen
Freedom of Information Officer
Village of Bensenville



Bensenville Fire Department

500 S. York Road, Bensenville IL 60106
Non-Emergency (630) 350-3441 Emergency 911 Fax (630) 350-3427

Jack Barba, Fire Chief
(630) 350-3443

April 23, 2004
Gravure Ink
1077 Sesame St.
Bensenville, IL 60106

Re: business license

Dear Gravure Ink,

An inspection of your facility was conducted on April 22nd. The following list of violations discovered need to be corrected before your business license can be issued :

- A frozen exterior sprinkler connection is seen on the west wall by the sprinkler system control valves. Please free up.
- Repair / replace the wood fence on the north end of the building. Property Maintenance Code Sec. 303.7.
- A permit is needed for the exterior business sign. Bensenville Sign Ordinance Sec. C-3.c
- Make extinguishers in the warehouse more " VISIBLE ". NFPA 10 Sec. 1-6.3 and 1-6.6
- Test all emergency lights monthly. Life Safety Code Sec. 5-9.3.
- Your business is considered a High Hazard. Per Village of Bensenville Building Code you are to install a 2-1/2" standpipe system per village specifications.

As discussed, with Debbie, Al, and Don, review your practices on grounding and bonding of the flammable liquid drums in the flammable liquids room. Test for a proper ground. I have information on this if you need it. Another item discussed was the integrity of the flammable liquids room and the need for closing the rolling overhead door. I will include you a copy of the code section which states: "doors can stay open **during material handling operations** provided they are designed to close automatically in a fire emergency." Please send me a current list of your flammable liquids and the amounts you have normally in storage.

There are other issues with the property that I need to direct to Darwin Asset Management. I will be in contact with Anthony Cesaretti.

"HELP US PREVENT FIRES"

If you have any questions you may call me at 630 – 350 – 3416.

Sincerely,

Dick Davis
Bureau Inspector

“HELP US PREVENT FIRES”



Bensenville Fire Department

500 S. York Road, Bensenville IL 60106
Non-Emergency (630) 350-3441 Emergency 911 Fax (630) 350-3427

Jack Barba, Fire Chief
(630) 350-3443

May 13, 2004

Debra Elderkin
Gravure Ink
1077 Sesame St.
Bensenville, IL 60106

Re: flammable liquids storage

Dear Debra,

As you may remember I had conducted a business license inspection at your facility on April 22nd. I have some concerns regarding your storage operations of the flammable liquids. According to information found on the MSDS sheets you have kindly supplied me with, some of these liquids are very hazardous. Two of these liquids have explosive capabilities, while other liquids require extinguishing agents other than water.

Part of my responsibility is to make sure you and your employees are safe and your operations meet code requirements for proper life safety and storage of these flammables. Due to the complex nature of flammable liquid storage and their requirements, I am asking you to retain the services of a fire code specialist of your choice to survey your operation. I would then like to meet with you and your consultant to discuss the findings. If you need names of a consultant I can supply you with a list.

Please schedule a meeting with your consultant and myself prior to June 4th, 2004. The codes that we follow which would apply to your situation are the Life Safety Code 101, 1997 Edition, BOCA Building Code, 1999 Edition and NFPA 30 1996 Edition.

If you have any questions you may call me at 630 – 350 – 3416.

Sincerely,

Dick Davis
Bureau Inspector

“HELP US PREVENT FIRES”



Bensenville Fire Department

500 S. York Road, Bensenville IL 60106

Non-Emergency (630) 350-3441 Emergency 911 Fax (630) 350-3427

Jack Barba, Fire Chief
(630) 350-3443

August 23, 2004

Debra Elderkin
Gravure Ink
1077 Sesame Street
Bensenville, IL. 60106

Re: flammable liquids storage room

Dear Debra,

I have reviewed the letter dated June 25, 2004 from Dave Eglsayer at U.S. Fire Protection.

In this letter he details the scope of the work to be completed to bring your liquids room into code requirements. After conferring with Dave I feel it is appropriate to grant you permission to begin scheduling this work. As you had asked, you will have until December 31, 2004 to complete this renovation.

Flammable liquids rooms such as yours are a challenge to properly protect. I thank you for your prompt attention and cooperation in completing these needed upgrades which will make your building not only safer for your employees, but also for emergency personnel.


Sincerely,

Dick Davis
Bureau Inspector

“HELP US PREVENT FIRES”

Village of Bensenville
Department of Community and Economic Development
12 S. Center Street, Bensenville, IL 60106
Phone: 630.350.3413 Fax: 630.350.3449

CERTIFICATE OF COMPLIANCE



TOM KNIGHT

Village of Bensenville Inspector

Tom Knight

Village of Bensenville Inspector's Signature

KEEP THIS CERTIFICATE WITH YOUR DEED AND OTHER VALUABLE DOCUMENTS



BENSENVILLE

WHERE OPPORTUNITY TAKES OFF

Thank you for purchasing your 2016 Business License

Watch for one of our Village Inspectors to visit you soon for your annual inspection.

GRAVURE INK/ ADORN L L C
1077 SESAME STREET
FRANKLIN PARK, IL 60131

"We are here to help"
----- Questions? -----
Call us at 630.350.3413

DISPLAY IN A PROMINENT LOCATION	VILLAGE OF BENSENVILLE BUSINESS LICENSE	LICENSE NUMBER 2088
<div style="font-size: 48px; opacity: 0.5; position: absolute; top: 0; left: 0; right: 0;">2016</div> <p style="margin: 0;">GRAVURE INK/ ADORN L L C</p> <p style="margin: 0;">1077 SESAME STREET</p> <p style="margin: 0;">BENSENVILLE COMMUNITY & ECONOMIC DEVELOPMENT</p>		
 <hr style="width: 80%; margin: 0 auto;"/> VILLAGE PRESIDENT	NON-TRANSFERABLE EXPIRATION DATE: 12/31/16	 <hr style="width: 80%; margin: 0 auto;"/> DIRECTOR OF COMMUNITY AND ECONOMIC DEVELOPMENT

FOR YOUR RECORDS	VILLAGE OF BENSENVILLE BUSINESS LICENSE	LICENSE NUMBER 2088
<div style="font-size: 48px; opacity: 0.5; position: absolute; top: 0; left: 0; right: 0;">2016</div> <p style="margin: 0;">GRAVURE INK/ ADORN L L C</p> <p style="margin: 0;">1077 SESAME STREET</p> <p style="margin: 0;">BENSENVILLE COMMUNITY & ECONOMIC DEVELOPMENT</p>		
 <hr style="width: 80%; margin: 0 auto;"/> VILLAGE PRESIDENT	NON-TRANSFERABLE EXPIRATION DATE: 12/31/16	 <hr style="width: 80%; margin: 0 auto;"/> DIRECTOR OF COMMUNITY AND ECONOMIC DEVELOPMENT



Bensenville Fire Department

500 S. York Road, Bensenville IL 60106
Non-Emergency (630) 350-3441 Emergency 911 Fax (630) 350-3427

Jack Barba, Fire Chief
(630) 350-3443

May 8, 2004

Mr. Anthony Cesaretti
Darwin Asset Management
970 N. Oakton Ave. Suite 100
Elmhurst, IL 60106

Re: 1077 – 1081 Sesame St.

Dear Anthony,

The building listed above is currently in violation of Village of Bensenville Building, Zoning, Fire, Property Maintenance Codes, and the Illinois Plumbing Code Part 890.

The following is a violation of the Village of Bensenville Building Code:

- All buildings in Use Group H over 50,000 sq. ft. are required to install 2-1/2" standpipe connections at each exit door, supplied by a separate 4" minimum riser .

The following are violations of the Village of Bensenville Zoning Code:

- A screened enclosure is required for exterior dumpsters and stored materials. Sec. 10-12-2D
- A screened enclosure is required for all roof top mechanical units protruding above a roof or parapet line. Sec. 10-12-2D
- Sealcoat maintenance is required for the asphalt surfaces. Sec. 10-11-8-2.3

The following is a violation of the Illinois Plumbing Code Part 890:

- Backflow prevention devices are overdue for annual inspections. Sec. 1130b

The following is a violation of the Village of Bensenville Fire Code Sec. 1-2.1:

- The building sprinkler system is impaired by painted, foil wrapped, and missing sprinkler heads.

“HELP US PREVENT FIRES”

The following are violations of the Village of Bensenville Property Maintenance Code:

- The wooden fence on the north end of the building is in need of repair / replacement. Sec. 303.7
- Weed control is needed. Sec.303.4

Provide copies to this office of current annual inspection reports for the fire pump, fire alarm and sprinkler systems. Per code, these reports are to be maintained on the premises. Please make accommodations for this.

Please respond by letter within 10 days of receipt of this letter. Indicate your intentions in regards to correcting these violations, and a schedule of correction completion. If you have any questions you may call me at 630 – 350 – 3416.

Sincerely,

Dick Davis
Bureau Inspector

“HELP US PREVENT FIRES”



VILLAGE OF BENSENVILLE
INSPECTIONAL SERVICES
 12 South Center
 Bensenville, IL 60106
 630-350-3413 fax:630-350-3449

Type of Inspection: NON-RESIDENTIAL INSPECTION

CORRECTION NOTICE

Address: 1081 SESAME STREET Unit:
 Business name:: AETNA BEARING Phone:
 Business Owner: JAMES TRAUSSCHT Address: S UNKNOWN STREET HINSDALE, IL
 Inspection Date: 05-27-2015 Inspector: TOM KNIGHT

<u>Checklist #</u>	<u>Violation</u>	<u>Violation comment</u>
120I	REMOVE ALL EXTENSION CORDS	Remove multi-tap plug and discontinue use (near shipping).
120J	DEDICATED RECEPTACLE NEEDED	Consider a dedicated receptacle or secure the power strip (near shipping).
150D	BATHROOM NEEDS EXHAUST FAN	Bathrooms must have mechanical ventilation that vents to the outside. Provide each bathroom with exhaust fan.
160	LIFE SAFETY REQUIREMENTS	Remove EXIT light next to the overhead door (east side).
160C	EXIT LIGHTS	Repair/replace EXIT lights. 90-minute battery back-up required.
160D	EMERGENCY LIGHTS	Test all emergency lights out of reach of the inspector.
160E	EMERGENCY LIGHTS	Repair/replace as needed. 90-minute battery backup required.
170A	HOSE CABINETS	Repair/replace emergency light (2nd floor office). 90-minute battery back-up required.
170G	MISSING ESCUTCHEON RINGS	Fire hose stations are not required. Removal is recommended, provide a brass cap for the male ends.
170J	STORZ FIRE DEPARTMENT CONNECTION (FC	Several sprinkler heads in the office area are missing heads and are not retained in position. Consult your sprinkler contractor.
180M	DROP TEST - ANNUALLY	Replace existing wye-type FDC with a 4"x4" STORZ type. Consult your fire sprinkler contractor.
		Rolling window shutters require annual testing/inspection. Provide current test sticker and post on the jamb.

Additional Remarks/Comments:

*****Please call for re-inspection before Nov. 15th. Thank you*****

Reinspection 38972 created on 10/15/2015
 by 6523tkni

THOSE ITEMS LISTED ABOVE ARE VIOLATIONS OF BENSENVILLE'S ADOPTED VILLAGE CODE AND/OR PROPERTY MAINTENANCE CODE. THIS IS YOUR WRITTEN "CORRECTION NOTICE". FAILURE TO CORRECT THE ABOVE LISTED VIOLATIONS WITHIN THE PRESCRIBED TIME CAN RESULT IN A FINE OF UP TO \$750 PER VIOLATION, PER DAY.

You are hereby notified to remedy the conditions as stated above within 30 days from the date of this order. Appeal from this order may be made within 20 days from the above date of service. Direct such appeal for a hearing before the Bensenville Board of Appeals in writing through the Director of Inspectional Services, 12 South Center.

Neither this inspection nor any Certificate of Occupancy issued by the Village of Bensenville shall be considered a complete list of Code or Municipal Ordinances. Our inspection can be substantially limited by access available and stored items or furniture. Some occupancies may require inspections to be completed on individual systems such as heating appliances, roofing, structure or fire protection systems. If you have questions about this inspection, please call 630-350-3448.



VILLAGE OF BENSENVILLE
INSPECTIONAL SERVICES
12 South Center
Bensenville, IL 60106
630-350-3413 fax:630-350-3449

Type of Inspection: NON-RESIDENTIAL INSPECTION

CORRECTION NOTICE

Address: 1081 SESAME STREET Unit:
Business name:: AETNA BEARING Phone: [REDACTED]
Business Owner: JAMES TRAU SHT Address: S UNKNOWN STREET HINSDALE, IL
Inspection Date: 05-27-2015 Inspector: TOM KNIGHT

DISCLAIMER: The Village of Bensenville does not warrant the condition of any property inspected and disclaims all liability for any claims arising out of the property or condition thereof.

Copy of this report received by/mailed to: Joe Amaro via email at joeamaro@aetnabearing.com

Inspector: Tom Knight Date: 10-15-2015



BENSENVILLE

WHERE OPPORTUNITY TAKES OFF

Thank you for purchasing your 2016 Business License

Watch for one of our Village Inspectors to visit you soon for your annual inspection.

AETNA BEARING
1081 SESAME STREET
FRANKLIN PARK, IL 60131

"We are here to help"
----- Questions? -----
Call us at 630.350.3413

DISPLAY IN A PROMINENT LOCATION	VILLAGE OF BENSENVILLE BUSINESS LICENSE	LICENSE NUMBER 2510
------------------------------------	--------------------------------------------	------------------------

2016

AETNA BEARING
1081 SESAME STREET
BENSENVILLE
COMMUNITY & ECONOMIC
DEVELOPMENT

 <hr style="width: 80%; margin: 0 auto;"/> VILLAGE PRESIDENT	NON-TRANSFERABLE EXPIRATION DATE: 12/31/16	 <hr style="width: 80%; margin: 0 auto;"/> DIRECTOR OF COMMUNITY AND ECONOMIC DEVELOPMENT
-----------------------------------------------------------------	-----------------------------------------------	-------------------------------------------------------------------------------------------------

FOR YOUR RECORDS	VILLAGE OF BENSENVILLE BUSINESS LICENSE	LICENSE NUMBER 2510
------------------	--------------------------------------------	------------------------

2016

AETNA BEARING
1081 SESAME STREET
BENSENVILLE
COMMUNITY & ECONOMIC
DEVELOPMENT

 <hr style="width: 80%; margin: 0 auto;"/> VILLAGE PRESIDENT	NON-TRANSFERABLE EXPIRATION DATE: 12/31/16	 <hr style="width: 80%; margin: 0 auto;"/> DIRECTOR OF COMMUNITY AND ECONOMIC DEVELOPMENT
-----------------------------------------------------------------	-----------------------------------------------	-------------------------------------------------------------------------------------------------



United States Alliance Fire Protection, Inc.

A Division of API Group, Inc.

28427 N. Ballard Road, Unit H - Lake Forest, IL 60045-4542 P: (847)-816-0050 / F: (847)-816-0098

www.usafireprotectioninc.com

Fire Sprinklers • Design/Installation • Testing • Maintenance • Inspections • 24 Hr Emergency Service

IL License # FSC 0032

Date: November 14, 2014

Value Industrial Partners, LLC
970 N. Oaklawn Ave.
Ste. 300
Elmhurst, IL 60126

Phone: 630-333-1900

Fax: 630-333-1910

Kristy Conte

Job #: 368305

FIRE SPRINKLER SYSTEM INSPECTION COMMENTS

United States Alliance Fire Protection has completed our inspection of the fire sprinkler system at this location:

1077 Sesame

1077 Sesame

Bensenville, IL 60106

During our inspection on 11/14/14, the following condition(s) were noted on our report:

- 1 SYSTEM(S) NOT TAGGED FOR ASSESSMENT OF INTERNAL CONDITION OF PIPING. (5) YEAR ASSESSMENT OF INTERNAL CONDITION OF PIPING REQUIRED PER NFPA 25.
- 2 CHECK VALVE(S) NOT TAGGED FOR INTERNAL INSPECTION. (5) YEAR CHECK VALVE INTERNAL INSPECTION REQUIRED PER NFPA 25.
- 3 (1) SPRINKLER HEAD UNDER GARAGE DOOR NEXT TO RISER MISSING DEFLECTOR. SERVICE REQUIRED TO REPLACE PER NFPA
- 4 (1) SPRINKLER HEAD UNDER GARAGE DOOR NEXT TO RISER PUSHED OUT OF PLACE. SERVICE REQUIRED PER NFPA
- 5 (3) WATER GAUGES ARE OVER 5 YEARS OLD. SERVICE REQUIRED TO REPLACE PER NFPA
- 6
- 7
- 8
- 9

Please note that the above pricing has been provided for budgetary purposes only. Please contact USAFP to receive consolidated pricing. By combining services there will be a "Cost Savings". Additional terms and conditions will apply. Please contact our office for details on terms and conditions as well as consolidated pricing.

Sincerely,

UNITED STATES ALLIANCE FIRE PROTECTION

Deb Frazier

Deb Frazier - Service Representative
(224) 433-5653
deb.frazier@usafp.us

Owner / Occupant

Signature

Date

Purchase Order

UNITED STATES ALLIANCE FIRE PROTECTION - INSPECTION REPORT - Page 1

USAFP Job Number: 368305

November 14, 2014

Inspection Authorized By

Location of Inspection

Company:	Value Industrial Partners, LLC		
Address:	970 N. Oaklawn Ave.		
Address:	Ste. 300		
City:	Elmhurst, IL 60126		
Contact:	Kristy Conte		
Phone:	630-333-1900	Fax #	630-333-1910

Name:	1077 Sesame		
Address:	1077 Sesame		
Address:			
City:	Bensenville, IL 60106		
Contact:	Liz Giammarese		
Phone:	630-333-1900	Fax #	0

Owner's Section (To be answered by Owner or Occupant)

A. Explain any occupancy hazard changes since the previous inspection.....	NONE
B. Describe fire protection modifications made since last inspection.....	NONE
C. Describe any fires since last inspection.....	NONE
D. When was the system piping last checked for stoppage, corrosion or foreign material?.....	ORIGINAL INSTALL 1972
E. When was the dry-piping system last checked for proper pitch?.....	NOT APPLICABLE
F. Are dry valves adequately protected from freezing?.....	NOT APPLICABLE

Owner's Insurance Co: _____ Agent: _____ Policy # _____

Owner's Representative: _____ Title: _____ Date: _____

Inspector's Section - Inspection Criteria in Accordance with NFPA 25

N/A = Not Applicable

1. General

a. Is the building occupied? YES NO

b. Are all systems in service? YES NO

c. Is there a minimum of 18" clearance between the top of the storage and the sprinkler deflectors? YES NO

d. Does all electrical heat tape appear to be satisfactory? YES NO N/A

e. Does the hand hose on the sprinkler system(s) appear to be satisfactory? YES NO N/A

2. Control Valves (Refer to Item 9.)

a. Are all sprinkler system control valves and all other valves in the appropriate open or closed position? YES NO

b. Are all control valves in the open position locked, sealed or equipped with a tamper switch? YES NO

3. Water Supplies (Refer to Item 10.)

a. Was a water flow test of main drain made at the sprinkler riser(s)? Date of the pressure gauge(s): 2006 YES NO

4. Tanks, Pumps, Fire Department Connections

a. Are fire pumps, gravity tanks, reservoirs and pressure tanks in good condition and properly maintained? YES NO N/A

b. Are fire department connections in satisfactory condition, couplings free, caps in place, and check valves tight? YES NO N/A

c. Are the fire department connections accessible and visible? YES NO N/A

5. Wet Systems

a. Are cold weather valves (O.S. & Y.) in the appropriate open or closed position? YES NO N/A

b. Have antifreeze system solutions been tested? Type of Anti-Freeze: Glycerin Propylene Glycol YES NO N/A

c. Were the antifreeze test results satisfactory? (Refer to item Table A.5.b for testing results - Page 4) YES NO N/A

d. Does the building appear to be properly heated in all areas, including blind attics and perimeter areas where accessible? YES NO N/A

e. Do all exterior openings appear to be protected against freezing? YES NO N/A

6. Alarms

a. Did water motor(s) and gong(s) test satisfactorily? YES NO N/A

b. Did electric alarm(s) test satisfactorily? YES NO N/A

c. Did supervisory alarm service test satisfactorily? YES NO N/A

7. Sprinklers

a. Are all sprinklers free from corrosion, loading or obstruction to spray discharge? YES NO

b. Are sprinklers less than 50 years old? (Older sprinklers require sample testing) Date: 1972 YES NO

c. Are quick response & residential sprinklers less than 20 years old? (Older sprinklers require sample testing) YES NO N/A

d. Is stock of spare sprinklers available? 6 Head Box 12 Head Box 24 Head Box 36 Head Box YES NO

e. Are sprinklers of proper temperature ratings for their locations? YES NO

8. Explain any "No" answers and comments:

6B LOCAL BELL FLOW SWITCH ON RISER #3 IS CORRODED INTERNALLY. SERVICE REQUIRED ((4" SADDLEBACK)

UNITED STATES ALLIANCE FIRE PROTECTION - INSPECTION REPORT - Page 2

9. Control Valve Maintenance - Refer to Table

Control Valve Maintenance Table

No.	Control Valves	Qty	Size	Type	Make	Secured	Open	Notes
1	City Side of Backflow	1	8"	OS&Y	KENNEDY	TAMPERED	YES	PUMP ROOM
2	System Side of Backflow	1	8"	OS&Y	KENNEDY	TAMPERED	YES	PUMP ROOM
3	System Control(s)	3	4"	WPIV	TCIW	TAMPERED	YES	UNIT 1077
4	System Control(s)	1	4"	OS&Y	KENNEDY	TAMPERED	YES	UNIT 1077
5	Fire Pump By-Pass	2	8"	OS&Y	NIBCO	TAMPERED	YES	PUMP ROOM
6	Fire Pump Suction	1	8"	OS&Y	NIBCO	TAMPERED	YES	PUMP ROOM
7	Fire Pump Discharge	1	8"	OS&Y	NIBCO	TAMPERED	YES	PUMP ROOM
8	Jockey Pump	2	1 1/2"	OS&Y	NIBCO	NO	YES	PUMP ROOM
9	Fire Pump Test	1	8"	OS&Y	NIBCO	TAMPERED	NO	PUMP ROOM
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								

Check Valve Maintenance Table

No.	Check Valves	Qty	Size	Type	Make	Model	Year	Notes
1	FDC Check Valve(s)	1	4"	WAFFER	TCIW		1972	
2	Fire Pump Discharge							
3	Fire Pump By-Pass							
4	Jockey Pump Check Valve(s)							
5	Dry System Check Valve(s)							

9. Explain any control valve deficiencies or abnormal conditions:



FIRE PUMP TEST DATA

ROGERS PUMP

16 S. Washington Ave.
 Batavia IL 60510
 Ph. 630-879-7747 Fax. 630-879-7742

Date: 11/17/2015

FOR: United States Alliance Fire Protection
28427 N Ballard Rd Unit H
Lake Forest IL 60045

LOCATION: 1077 - 1081 Sesame
Bensenville IL 60131

FIRE PUMP

MFR Aurora
 SIZE 6x8x18B TYPE 481 STAGE 1
 RPM 1770 SERIAL 02-430420
 IMPELLER 15.875 GPM 1500 PSI 100
 MAX PRESSURE 120 150% PRESSURE 75

FIRE PUMP MOTOR

MFR Marathon HP 125
 RPM 1780 AMPS 147 VOLTS 460
 HZ 60 SERIAL MB859730-3
 ENCLOSURE DP TYPE TDS
 COUPLING Woods FRAME 405TS

JOCKEY PUMP

MFR Aurora
 MODEL IO5-BF SERIAL 02-430420

JOCKEY PUMP MOTOR

MFR Marathon HP 5
 RPM 3450 VOLTS 208

RPM	VOLTS			AMPS			SUCT	DISH	NET	PITOT TUBE					GPM
1795	486	486	485	84	82	80	47	170	123	C H U R N					0
1787	484	484	483	142	140	136	30	134	104	13	13	11	10	10	1533
1784	482	481	484	158	156	154	11	93	82	26	26	23	24	25	2267
1796	483	483	483	82	81	79	48	171	123	C H U R N					0

4 ALARMS NEED TO BE TAKEN OUT OF SERVICE PRIOR TO TEST - NEED 25FT OF HOSE PER LINE

FIRE PUMP
 CONTROLLER Joslyn Clark
 SER# 221399-01
 CAT# C7C214-4
 VOLT 460 HP 125

JOCKEY PUMP
 CONTROLLER Joslyn Clark
 SERIAL 225935
 MOD# JSNE10AB3293-26TS-F5/200
 VOLT 208 HP 5

	ON	OFF
JOCKEY PUMP	130	140
ELECTRIC - FIRE PUMP	120	130
DIESEL - FIRE PUMP		
FIRE PUMP RUN TIMER	10 Minute	

AUTO START MANUAL START EMERGENCY START NOZZLE SIZE

IN ATTENDANCE AT TEST

FIRE DEPT: Bensenville
 REP: Tony Bagnola
 SPRINKLER CONTRACTOR: _____
 REP: _____
 DIESEL MFR: _____
 REP: _____
 INSURANCE CO: _____
 REP: _____

BLDG REP: N/A
 SIGNATURE: _____
 CONTROLLER MFR: _____
 REP: _____
 PUMP MFR: Aurora
 REP: Rogers Pump
 REP: John Rauen - DJ Clienmark

COMMENTS: _____

VILLAGE OF BENSENVILLE

NON-RESIDENTIAL PERMIT APPLICATION

DEPARTMENT OF COMMUNITY AND ECONOMIC DEVELOPMENT
PHONE: 630.350.3413 FAX: 630.350.3449

12 S. CENTER STREET
BENSENVILLE, IL 60106

PERMIT INFORMATION

INCOMPLETE APPLICATIONS WILL NOT BE ACCEPTED

1077 Sesame St. I-4
 SITE ADDRESS UNIT NUMBER ZONING DISTRICT
 roof overlay over existing system
 DESCRIPTION OF WORK 1 P.L.N. (Parcel Identification Number)
 DESCRIPTION OF WORK 2 92000 ESTIMATED COST

CONTRACTOR INFORMATION

GENERAL CONTRACTOR Email Address Day Time Phone
 Address City, State, & ZIP Code
 LICENSED PLUMBING CONTRACTOR Email Address Day Time Phone
 Address City, State, & ZIP Code
 LICENSED ELECTRICAL CONTRACTOR Email Address Day Time Phone
 Address City, State, & ZIP Code
 RAM Services
 ROOFING CONTRACTOR Email Address Day Time Phone
 18304 Maple St. Lansing IL 60438
 Address City, State, & ZIP Code

OWNER & APPLICANT INFORMATION

No error or omission in either the plans or application shall relieve the applicant in having the work completed in any other manner than that which is in compliance with the approved plans and the applicable codes and ordinances of the Village of Bensenville and the State of Illinois. All work shall be completed, inspected, and approved as required and no occupancy or use of the space shall be permitted until approved in writing by the Department of Community and Economic Development. Understanding the preceding statements, I hereby agree to comply and declare that to the best of my knowledge and belief the information provided is true and accurate.

Cynthia J Holsapple 7/26/13
 Applicant's Name (Print) Applicant's Signature Date
 18304 Maple St Lansing IL 60438
 Address City, State, & ZIP Code Day Time Phone
 Correspondence and escrow refunds can only be completed if the address of the applicant is kept current, which is the applicant's responsibility.
 I hereby authorize the above listed applicant to complete the provisions of the applicable code and ordinances for this permit.
 John Horrigan
 Property Owner's Name (Print) Property Owner's Signature Date
 970 Oaklawn Ave Elmhurst IL
 Address City, State, & ZIP Code Day Time Phone

Patrick Industries Gravure Inc.

APPLICATION NUMBER 3644

BUILDING INFORMATION (PLEASE check all that apply)

New Construction Addition Alteration Accessory
 INTENDED USE:
 Assembly / Restaurant Institutional / Medical Factory / Industrial
 Mercantile / Retail Storage / Warehouse Business / Office
 Other _____
 Single Tenant Building Multiple Tenant Building (# of Tenants _____)
 Existing Fire Alarm? Yes No
 Existing Sprinkler System? Yes No
 Full Building Coverage? Yes No [% of coverage _____]
 Name of Business on Site _____
 Description of Operations _____
 Existing Sq.Ft. _____ New Sq.Ft. _____ Total Sq.Ft. _____

OFFICE USE ONLY

FEES:	WILESTONE DATES:
ESCROW \$ 200.00	Applied on: 7/26/13
APPLICATION \$ 30.00	Approved on: 7/29/13
PLAN REVIEW \$.00	Issued on: 07/30/13
INSPECTIONS (1 X \$50) \$ 50.00	Expires on: 01/30/14
WATER CONNECTION \$.00	Approved by:
WATER METER \$.00	
SEWER CONNECTION \$.00	
FIRE METER \$.00	
OTHER \$.00	
TOTAL PERMIT FEE: \$ 280.00	

*All failed inspections will be charged against the escrow at the standard inspection rates. After final approvals and occupancy have been issued, the remaining escrow will be refunded to the payee via first class mail. In the event the cost of failed inspections exceeds the escrow amount, no further inspections will be completed until an additional escrow has been received.

VILLAGE OF BENSENVILLE

NON-RESIDENTIAL PERMIT APPLICATION

DEPARTMENT OF COMMUNITY AND ECONOMIC DEVELOPMENT
PHONE: 630.350.3413 FAX: 630.350.3449

12 S. CENTER STREET
BENSENVILLE, IL 60106

PERMIT INFORMATION

INCOMPLETE APPLICATIONS WILL NOT BE ACCEPTED

157781 Sesame
SITE ADDRESS
Water main repair
DESCRIPTION OF WORK 1
DESCRIPTION OF WORK 2
UNIT NUMBER
ZONING DISTRICT
P.I.N. (Parcel Identification Number)
5000
ESTIMATED COST

APPLICATION NUMBER 4221

BUILDING INFORMATION (PLEASE check all that apply)

New Construction Addition Alteration Accessory

INTENDED USE:
 Assembly / Restaurant Institutional / Medical Factory / Industrial
 Mercantile / Retail Storage / Warehouse Business / Office
 Other _____
 Single Tenant Building Multiple Tenant Building (# of Tenants _____)

Existing Fire Alarm? Yes No
Existing Sprinkler System? Yes No
Full Building Coverage? Yes No (% of coverage _____)

Name of Business on Site _____
Description of Operations _____
Existing Sq.Ft. _____ New Sq.Ft. _____ Total Sq.Ft. _____

CONTRACTOR INFORMATION

U.S.A Fire Protection
GENERAL CONTRACTOR
Email Address _____ Day Time Phone _____
Address _____ City, State, & ZIP Code _____
LICENSED PLUMBING CONTRACTOR
Email Address _____ Day Time Phone _____
Address _____ City, State, & ZIP Code _____
LICENSED ELECTRICAL CONTRACTOR
MAY 12 2014
Email Address _____ Day Time Phone _____
Address _____ City, State, & ZIP Code _____
ROOFING CONTRACTOR
Email Address _____ Day Time Phone _____
Address _____ City, State, & ZIP Code _____

OFFICE USE ONLY

FEES:	MILESTONE DATES:
ESCROW * \$200.00	Applied on: 5-12-14
APPLICATION \$30.00	Approved on: SAME
PLAN REVIEW \$.00	Issued on: 5-12-14
INSPECTIONS (3 X \$50) \$150.00	Expires on: 11-12-14
WATER CONNECTION \$.00	
WATER METER \$.00	
SEWER CONNECTION \$.00	Approved by: MF
FIRE METER \$.00	
OTHER \$.00	
TOTAL PERMIT FEE \$380.00	

OWNER & APPLICANT INFORMATION

No error or omission in either the plans or application shall relieve the applicant in having the work completed in any other manner than that which is in compliance with the approved plans and the applicable codes and ordinances of the Village of Bensenville and the State of Illinois. All work shall be completed, inspected, and approved as required and no occupancy or use of the space shall be permitted until approved in writing by the Department of Community and Economic Development. Understanding the preceding statements, I hereby agree to comply and declare that to the best of my knowledge and belief the information provided is true and accurate.

Next Marshall
Applicant's Name (Print) _____ Applicant's Signature _____ Date 5/12/14
970 W. Oak Lawn Ave
Address _____ City, State, & ZIP Code 60126
Day Time Phone _____

Correspondence and escrow refunds can only be completed if the address of the applicant is kept current, which is the applicant's responsibility.

I hereby authorize the above listed applicant to complete the provisions of the applicable code and ordinances for this permit.

VIP Sesame, LLC
Property Owner's Name (Print) _____ Property Owner's Signature _____ Date 5/12/14
970 W. Oak Lawn Ave
Address _____ City, State, & ZIP Code 60126
Day Time Phone _____

*All failed inspections will be charged against the escrow at the standard inspection rates. After final approvals and occupancy have been issued, the remaining escrow will be refunded to the payee via first class mail. In the event the cost of failed inspections exceeds the escrow amount, no further inspections will be completed until an additional escrow has been received.